

Dist	Co No	Sta	Operator	Type	Yr	Lic No	Make	Model	Vin No
NDL5815	5815	31	UT31	UTILITY 4X4 2	2003	1205453	FORD	F350	1FTSW31S53EA18252
NDL19304	19304	31	WT31	WATER TENDER T1	1978	452430	FORD	L9000	W91AVBF0263
NDL18342	18342	31	E31	ENGINE 1	2005	1209261	KME	EXCEL 5914	1K9AF42845N058921
NDL18324	18324	31	BP31	ENGINE 6	2003	1152567	FORD/ROSENBAUER	F550 4X4	1FDAW57P63ED01197

**Rick Daniels**

---

**Subject:** 18342 (ME31) REpairs August 2015

**Subject:** 18342 (ME31)

Good morning Steve,

The shop has 18342 (ME31) in here for some major repairs and I just wanted to let you know about the needed repairs costs.

- |   |  |
|---|--|
| 1. Tow unit from Station 31 to shop.                                    | Labor \$1,113.00                                       |
| 2. Replace rear springs due to military wrap broke.                     | Labor \$1,700.00 Parts \$3,300.00                      |
| 3. Align unit.  | Sublet \$250.00  |
| 4. Left rear cab mount sheared off of cab.<br>mount back on. \$1,500.00 | We prepped the unit and the tractor side will weld the |
| 5. Primer pump inop.  | Labor \$500.00 Parts \$250.00                          |
| 6. Ongoing buzzing in the firecom headsets.                             | Labor \$750.00 Parts \$300.00                          |
| 7. Replace rear axle brakes.  | Labor \$904.00 Parts \$903.48                          |
| 8. PMA  | Labor \$508.50 Parts \$399.39                          |
| 9. Transport unit back to Station 31.(bringing E17 back)                | Labor \$1,113.00                                       |

Total of \$14,000.00 approximately for parts and labor

**Doug Rand, Shop Supervisor**  
**S.B.C.F.D. Vehicle Services**  
**Office 909-387-7803**  
**Cell 909-292-7341**  
**[drand@sbcfire.org](mailto:drand@sbcfire.org)**